
220 VAC
L1
L2
120 VAC
N
11/19/2018
20 Amp Fuse
20 Amp Fuse
PS Isolated
PS 24 VDC
PS 5 VDC
PS 70 VDC
PS 70 VDC
PS 70 VDC
+ 24 VDC
X Left Limit
X Right Limit
Y Front Limit
Y Back Limit
Z Top Limit
Z Bottom Limit
X Home Limit
Home Left
Z Home Limit
Home Top
YL Home Limit
Home Front
YR Home Limit
Home Front
Enable All
E-Stop 1
E-Stop 2
Spindle ON
Spindle Off
Spindle
Control Power Switch
Cabinet Fan 120 Volt
Stepper Motor YL Axis
Stepper Motor YR Axis
Stepper Motor X Axis
Stepper Motor Z Axis
Stepper Motor 4th Axis
Optional Return Energy Dump
Gecko G210
Gecko G320X ServoDrive
Servo Motor 4th Axis
Encoder
Provision for 4th Axis to be either Stepper or Servo motor
Kanalog + 5 VDC Common to Gecko Drives
Fault LED
220 ohm
PN2907
Gecko Optional External Fault LED Circuit
4th Axis 6 Volt LED
Start
Stop Momentary Center Off
Delta VFD C2000
Spindle 3 HP Causing
Spindle cable ground wire and cable shield case ground both ends
Kanalog JP1
Kanalog JP5
Kanalog JP15
Optic Inputs
KFLOP JP4
KFLOP JP6
Optic Isolator
Relays are Allen Bradley 700-HF34Z24
To PS 5 VDC +V
To PS 5 VDC -V
Opto Isolated 8 relay board
ASIN B01N6WRLUL
Return Energy Dump
Supply +
Supply -
LED
1K ohm
10A10
1K ohm
TIP 147
8.2K ohm
1000uF 100V
33 ohm 10W
To Drive +
To Drive -
Limit switch cable shield connected only on one end to PS 24 VDC negative