

First verify you can successfully re-build KMotionCNC from source code:

- #1 - install VS 2008
- #2 - open the "solution" called <>\PC VC Examples\BuildExamples\BuildExamples.sln
- #3 - Right click KMotionCNC and set it as the "Start up" project
- #4 - set the Build Configuration as "Release"
- #5 - From the Build Menu select "Rebuild KMotionCNC"
- #6 - if successful push F5 to run KMotionCNC
- #7 - exit KMotionCNC

To Change a screen:

- #1 - from the View Menu select Resource View
- #2 - Open KMotionCNC | KMotionCNC.rc | Dialogs
- #3 - double-click a Dialog to change ie IDD_KMOTIONCNC_6_LATHE_2_AXES
- #4 - visually select cells to move/resize or change the cell's properties
- #5 - push F5 to compile and run the changed program